

## Dunbarton Tech Bulletin

### *Dunbarton Strike Dustboxes*

D-004.18

July 16, 2018

Effective July 30, 2018, Dunbarton will no longer be including dustboxes on strikes for RediFrame and RediFlex products. We have run into issues with installers having to notch out studs to fit the frames with dustboxes included. In speaking with customers, the overwhelming response has been to eliminate the dustbox on the strikes as a standard.

If you do require a dustbox for your application, specify on your order and we will include the dustbox on the strike hardware preparation.

Dustboxes will still be a standard on Dunbarton hollow metal frames.

If you have any questions, feel free to contact your Dunbarton sales rep or customer service professional.



**THE  
DUNBARTON  
GROUP**  
*Your Complete Opening Solution*

1101 Technology Drive | Dothan, Alabama 36303  
**800.633.7553** | 334.794.9184 fax  
www.dunbarton.com | sales@dunbarton.com